



Yokoyama Dam
(Managed by the Ministry of Land,
Infrastructure and Transport)

National road
Route 303

Town road
Shimoyama Route

Landslide site

Ibi River

Landslide site



Height: about 90 m

Collapse of sediment:
about 50,000 m³

Collapsed sediment covered
half the river width

Ibi River

State of sediment collapse



State of sediment collapse

Change of landslide displacement at Higashi-Yokoyama along the Ibi River
(measurement: extensometer)

